

ONETRAC LXD: SMOKE EVACUATION ADAPTER INSTRUCTIONS

Insert the smoke evacuation adapter into the universal suction port (located on both ends of the device). Twist the adapter to secure fitting. Connect suction tubing directly to adapter. This will initiate suction on the blade opposite the suction tubing.

SMOKE EVACUATION ADAPTER*

*Included with each unit.

